



Littleton, CO 80144
 Inspection prepared for:
 Date of Inspection: 12/24/2016 Time: 2:00 pm
 Age of Home: 1984 Size: 1550
 Weather: 60 Sunny

Exterior Areas

Page 8 Item: 3

Siding Condition


- **Sprinklers may be spraying side of house; check and readjust as necessary, to prevent siding damage by moisture or insects..**
- **Evidence of insect activity and/or insects around exterior of house. Recommend evaluation by licensed pest control specialist/exterminator. (observed evidence of bees living inside the bottom of the deck posts and possibly more next to the exterior door trim.**

2. Window Condition

Good	Fair	Poor	N/A	None
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Observations:

- Components appeared in satisfactory condition at time of inspection.



SAMPLE REPORT

General Info

We provide any key details such as time of day, weather conditions, and current age of the home. We also attach a photo for further confirmation.

Report Summary

The summary consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expense to correct or items that need extra attention.

The summary is not a complete listing of ALL the findings in the report, but does make finding the most important observations much easier.

Itemized Inspection

For each item inspected, we provide a Good/Fair/Poor rating, describe the condition of item (at time of inspection), and provide any notes based on our observation.

We may also include photos to clarify or further describe the current condition of any/all items.

Have Any Questions about a future inspection? Please Ask!

(303) 945-6393 | Info@PinnacleInspectionsDenver.com
 www.PinnacleInspectionsDenver.com